DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke **Executive Director**

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801

801-538-7223 (TDD)

Salt Lake City, Utah 84114-5801

Partial: XXX Complete: Exploration:

Inspection Date & Time: <u>6/29/2000 / 9:00a.m.-12:00p.m.</u> 801-538-5340 801-359-3940 (Fax)

Date of Last Inspection: 5/16/2000

Mine Name: Sunnyside Refuse/Slurry County: Carbon Permit Number: ACT/007/035						
Permittee and/or Operator's Name: Sunnyside Cogeneration Associates						
Business Address: P.O. Box 10, East Carbon, Utah 84520						
Type of Mining Activity: Underground Surface XXX Prep. Plant Other						
Company Official(s): Rusty Netz						
State Officials(s): Steve Demczak Federal Official(s): None						
Weather Conditions: Warm, 80's						
Existing Acreage: Permitted-310 Disturbed-202 Regraded- Seeded- Bonded-202						
Increased/Decreased: Permitted Disturbed Regraded Bonded						
Status:Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liability 1994 Course Refuse Road)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

Substantiate the elements on this inspection by checking the appropriate performance standard.

For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

For <u>partial inspections</u> check only the elements evaluated.

- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		\Box		\Box
2.	SIGNS AND MARKERS		Ш	\Box	\Box
3.	TOPSOIL	$\overline{\Box}$	$\overline{\square}$	\Box	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	\Box	[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	\Box	[XX]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	. []	\Box		
d.	WATER MONITORING		\Box	\Box	
e.	EFFLUENT LIMITATIONS		\Box		
5.	EXPLOSIVES	$\overline{\square}$	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	\Box	[XX]	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	\Box	[XX]	\Box
8.	NONCOAL WASTE	[XX]	\Box	[XX]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	\Box	\Box	
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		\Box	\Box	\Box
12.	BACKFILLING AND GRADING	\Box	\Box		\Box
13.	REVEGETATION	\Box	\Box		
14.	SUBSIDENCE CONTROL	\Box	\Box		\Box
15.	CESSATION OF OPERATIONS	\Box			
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	\Box	\Box
b.	DRAINAGE CONTROLS	\Box	\Box		
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box		
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		\Box	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)	\Box			
20.			\Box		\Box
21	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/035

DATE OF INSPECTION: 6/29/2000

(Comments are Numbered to Correspond with Topics Listed Above)

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were clean and would function if an event occurred.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The disturbed area contains eleven impoundments, seven of which are sediment ponds. The remainder are for slurry containment. Two of these are classified as MSHA impoundments. All slurry cells are inactive, since coal washing ceased when the Sunnyside Mine closed in March of 1994.

6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES

The permittee has a Division approved site to store spoil and tipple processing waste within the permit area. Reject material is disposed of in the decommissioned slurry cell #1, . When slurry cell #1 is full, the operation will move to slurry cell #2.

Three sites have been approved so that coal material is stored on spoil piles and not on the refuse pile.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee is currently mining the west slurry cell and the contiguous refuse pile. No mining has started on the east slurry cell.

No hazardous conditions were noticed during the inspection.

8. NON-COAL WASTE -

The area was clean of non-coal waste except for a few beverage cans located in the area where test drilling occurs. The permittee will remove these items.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Rusty Netz (Cogen)

Given to: Pam Grubaugh-Littig (DOGM)

Henry Austin (OSM)

Filed to: Price Field Office

Date: July 6, 2000

Inspector's Signature: #39

Stephen I Demozak